# **PROCEDURES**

# ABNORMAL AND EMERGENCY PROCEDURES

# A318/A319/A320/A321 FLIGHT CREW OPERATING MANUAL

**AUTO FLIGHT** 

AUTO FLT RUD TRIM 1(2) FAULT			
STATUS			
INOP SYS			
CAT 3 DUAL RUD TRIM 1(2)			

<u>AUTO FLT</u> RUD TRIM SYS			
Applicable to: ALL			
FAC 1FAC 2	OFF THEN ON OFF THEN ON		
STATUS			
	INOP SYS		
	RUD TRIM AP 1 + 2 CAT 2		

	AUTO FLT RUD TRV LIM 1(2)		
Applicable to: ALL			
Crew awareness.		Continued on t	he following page
A318/A319/A320/A321 FLEET		PRO-	-22 P 10/18
FCOM	I to K →		17 AUG 12

## **PROCEDURES**

#### ABNORMAL AND EMERGENCY PROCEDURES

A318/A319/A320/A321 FLIGHT CREW OPERATING MANUAL

**AUTO FLIGHT** 

## **AUTO FLT RUD TRV LIM 1(2) (Cont'd)**

**STATUS** 

**INOP SYS** 

RUD TRV LIM 1(2)

### **AUTO FLT RUD TRV LIM SYS**

Applicable to: ALL

#### **RUD WITH CARE ABV 160 KT**

Depending on when the failure occurs, the rudder travel limiter system may not be in the correct position for the flight speed. Therefore, to prevent damage to the aircraft structure, use the rudder with care, when the speed is greater than 160 kt.

At slats' extension, full rudder travel authority can be recovered.

□ FAC 1......OFF THEN ON FAC 2.....OFF THEN ON

• If TLU (rudder or pedals) remains locked at high speed after slat extension:

MAX X WIND FOR LDG 15 KT

AUTO BRK......DO NOT USE

Do not use the autobrake, so as not to delay the application of differential braking at landing roll.

■ AT LDG ROLL:

DIFF BRAKING...... AS RQRD

Continued on the following page

PRO-

## **PROCEDURES**

#### ABNORMAL AND EMERGENCY PROCEDURES

# A318/A319/A320/A321

**FLIGHT CREW OPERATING MANUAL**  **AUTO FLIGHT** 

## **AUTO FLT RUD TRV LIM SYS (Cont'd)**

L12

#### **STATUS**

#### **RUD WITH CARE ABV 160 KT**

If TLU (rudder or pedals) remains locked at high speed after slat extension:

MAX X WIND FOR LDG 15 KT

AUTO BRK...... DO NOT USE

Do not use the autobrake, so as not to delay the application of differential braking at landing roll.

• AT LDG ROLL:

DIFF BRAKING...... AS RQRD

CAT 3 SINGLE ONLY

Note: An autoland must not be performed with a crosswind greater than 12 kt.

# **AUTO FLT YAW DAMPER 1(2)**

Crew awareness.

The crew can try to reset the affected FAC by using the FAC pb-sw. On ground only, if the Note:

reset is unsuccessful, the taxi and takeoff can be continued with the failed yaw damper

inoperative.

**STATUS** 

**CAT 3 SINGLE ONLY** 

**INOP SYS** 

**INOP SYS** 

**RUD TRV LIM** 

CAT 3 DUAL

CAT 3 DUAL YAW DAMPER 1(2)