

FLIGHT OPERATIONS TELEX - FLIGHT OPERATIONS TELEX
FLIGHT OPERATIONS TELEX - FLIGHT OPERATIONS TELEX
SUBJECT: **ATA 27 - STALL RECOVERY PROCEDURE**

OUR REF.: 999.0044/10 dated May 12, 2010

CLASSIFICATION: AIRWORTHINESS

AFFECTED AIRCRAFT: This FOT is applicable to all Airbus aircraft

Notice: This FOT covers an operational issue.

It is the **Operators' responsibility to distribute this FOT or the information contained in this FOT to all flight crews without delay.**

1. PURPOSE

Recent industry events have drawn attention to the importance **of appropriate pilot reaction in the case of stall.**

This FOT informs all Airbus aircraft operators of the publication of a temporary revision (TR) to modify the stall recovery procedure.

2. DESCRIPTION

Reduction of the angle of attack must be the first immediate action upon stall recognition (aural stall warning, buffet, _).

Therefore a nose down pitch order must be applied.

When stall indications have stopped, the flight crew can smoothly increase the thrust as needed to increase the energy and recover the initial flight path.

Minimizing the loss of altitude is secondary to the reduction of the angle of attack.

This procedure is a memory item. It will be included in the QRH (except for A380).

3. FLIGHT OPERATIONAL RECOMMENDATIONS

Operators should implement this modified procedure upon receipt of the FOT.

4. TRAINING ADVICES

Academic training: Airbus recommends that the academic information of this subject be made available to all pilots, as soon as possible. A PowerPoint presentation will be available on the Airbus World portal.

Type rating training: The modified procedure has to be applied for all stall recovery procedures (including previous reference to approach to stall training).

Recurrent training: Airbus recommends to review the procedure in the next recurrent training cycle to reinforce the application of the procedure. Additionally the FAA stall training group will provide detailed guidance on stall training technique by the end of September 2010.

5. FOLLOW-UP ACTION PLAN

The stall recovery procedure is available on the Airbus world portal and will be dispatched to operators as follows:

A300/A310/A300-600/A300-600F aircraft :

A300 QRH Temporary Revision number 076-1

A300 FCOM volume 8GE Temporary Revision number 219-1

A300 FCOM volume 8PW Temporary Revision number 051-1

A300FFCC QRH Temporary Revision number 025-1

A300FFCC FCOM volume 2 Temporary Revision number 052-1

A300-600/A300-600F QRH Temporary Revision number 217-1

A300-600/A300-600F FCOM volume 2 Temporary Revision number 002-2

A300-600ST QRH Temporary Revision number 026-1

A300-600ST FCOM volume 2 Temporary Revision number 035-1

A310 QRH Temporary Revision number 224-1

A310 FCOM volume 2 Temporary Revision number 004-2

A318/319/320/321 aircraft:

FCOM volume 3 Temporary Revision number 323-1

QRH Temporary Revision number 727-1

A330 aircraft

FCOM volume 3 Temporary Revision number 552-1

QRH Temporary Revision number 353-1

A340 aircraft

FCOM volume 3 Temporary Revision number 512-1 (A340-200/-300)
FCOM volume 3 Temporary Revision number 513-1 (A340-500/-600)
QRH Temporary Revision number 369-1

A380 aircraft

FCOM Procedures / Non-ECAM Abnormal and Emergency Procedures / Operating Techniques

In addition, the Flight Crew Training Manual will be revised accordingly.

No additional follow up is planned.

Please submit questions about the operational content of this FOT to:

For A300/A310/A300-600/A300-600F aircraft

Mr Peiman TOFIGHI-NIAKI

Phone: +33 (0)5.67.19.16.96

Fax: +33 (0)5.61.93.29.68

E-mail: fltops.wbstd@airbus.com

For A318/A319/A320A321/A330/A340 aircraft

Mr. Xavier VILLAIN, STLS

Phone: +33 (0)5.62.11.02.94

Fax: +33 (0)5.61.93.29.68

E-mail: fltops.fbwstd@airbus.com

For A380 aircraft

Mr Bert PORTEMAN

Phone: +33 (0)5.67.19.02.19

Fax: +33 (0)5.61.93.29.68

E-mail: fltops.A380std@airbus.com

For training:

flightcrew.training-policy@airbus.com

Best regards,

Capt. Marc PARISIS

Vice President Flight Operations Support and Services

'If you receive this message via E-mail/internet, we draw your attention to the fact that it may be monitored and/or intercepted. Further, whilst Airbus has taken reasonable measures to ensure the integrity of this message and its contents, no warranty, whether express or implied, is given that the contents hereof conform to the original. In case of

any doubt, please retrieve this document from your SITA address or the AirbusWorld system or request that it be retransmitted by fax or telex.'

The information in this e-mail is confidential. The contents may not be disclosed or used by anyone other than the addressee. Access to this e-mail by anyone else is unauthorised.

If you are not the intended recipient, please notify Airbus immediately and delete this e-mail.

Airbus cannot accept any responsibility for the accuracy or completeness of this e-mail as it has been sent over public networks. If you have any concerns over the content of this message or its Accuracy or Integrity, please contact Airbus immediately.

All outgoing e-mails from Airbus are checked using regularly updated virus scanning software but you should take whatever measures you deem to be appropriate to ensure that this message and any attachments are virus free.